



**Underwriters  
Laboratories Inc.®**

**Melville Division**

1285 Walt Whitman Road  
Melville, NY 11747-3081 USA  
www.ul.com  
tel: 1 631 271 6200  
fax: 1 631 271 8259  
Customer service: 1 877 854 3577

**NOTICE OF AUTHORIZATION TO APPLY THE UL MARK**

March 30, 2007

Mr. John Graham  
Spellman High Voltage Electronics Corp.  
1 Commerce Park  
Valhalla, NY 10595

E-mail: johng@spellmanhv.com

Reference: File E231025 Project 07ME05112 PO# GRAHAM, JOHN MR.

Product: USR/CNR – Revision to E231025, Vol. 1, Sec. 1  
(Alternate Construction to Power supply, Model D3039)

Dear Mr. Graham,

Any information and documentation involving UL Mark services are provided on behalf of Underwriters Laboratories Inc. (UL) or any authorized licensee of UL.

UL's investigation of your product has been completed under the above project number and the subject product was determined to comply with the applicable requirements.

This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Recognized Marking and/or Recognized Component Mark only at the factory under UL's Follow-Up Service Program to the subject product, which is constructed as described below:

Similar to the subject model, which was submitted to UL for this investigation. The UL Records covering the product will be in the Follow-Up Services Procedure, File E231025, Volume 1.

This authorization applies only to the address on this letter.

This authorization is effective from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that Follow-Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

Products that bear the UL Mark shall be identical to those that were evaluated by UL and found to comply with UL's requirements. If changes in construction are discovered, appropriate action will be taken for products not in conformance with UL's requirements and continued use of the UL Mark may be withdrawn.

Sincerely,

Reviewed by:

Roy Y. Shinmachi  
Senior Engineering Associate  
Department: 3013AMEL  
Tel: (631) 271-6200, Ext. 22631  
E-mail: roy.y.shinmachi@us.ul.com

David V. Alma  
Staff Engineer  
Department: 3013AMEL  
Tel: (631) 271-6200, Ext. 22617  
E-mail: charles.v.comparetto@us.ul.com

